


SECTION 4.05

GROUND MARSHALLING DIRECTIONS

**GROUND MARSHALLING DIRECTIONS**

START ENGINE




LEFT HAND POINTING TO SPECIFIC UPRIGHT, RIGHT HAND MOVING IN A CIRCULAR MOTION AT HEAD LEVEL.

MOVE AHEAD



ARMS A LITTLE TO ONE SIDE MOVED REPEATEDLY UPWARDS AND BACKWARDS.

TURNS



ARM POINTING TO DIRECTION OF TURN OTHER ARM MOVED UP AND BACK. SPEED OF MOVEMENT SHOWS RATE OF TURN.

SLOW DOWN




ARMS DOWN CLOSE TO SIDE MOVED UP AND DOWN SEVERAL TIMES.

STOP



ARMS REPEATEDLY CROSSED ABOVE HEAD. (THE RAPIDITY OF THE ARM MOVEMENT SHOWS THE URGENCY OF STOP.)

CUT ENGINE



HAND LEVEL WITH SHOULDER, HAND MOVED SIDEWAYS ACROSS THE THROAT.

**THIS PAGE  
DELBERATELY  
BLANK**